

## DAFTAR ISI

	<b>Halaman</b>
<b>HALAMAN JUDUL .....</b>	<b>i</b>
<b>LEMBAR PENGESAHAN .....</b>	<b>ii</b>
<b>PERNYATAAN KEASLIAN KARYA ILMIAH .....</b>	<b>iii</b>
<b>HALAMAN PERSEMBAHAN .....</b>	<b>iv</b>
<b>PRAKATA .....</b>	<b>v</b>
<b>RINGKASAN .....</b>	<b>vi</b>
<b>ABSTRACT .....</b>	<b>vii</b>
<b>DAFTAR ISI.....</b>	<b>ix</b>
<b>DAFTAR GAMBAR.....</b>	<b>xi</b>
<b>DAFTAR TABEL .....</b>	<b>xii</b>
<b>DAFTAR LAMPIRAN.....</b>	<b>xiii</b>
<b>BAB I PENDAHULUAN.....</b>	<b>1</b>
I.1    Latar Belakang .....	1
I.2    Maksud dan Tujuan.....	2
I.3    Rumusan Masalah .....	2
I.4    Metodologi.....	3
I.5.    Sistematika Penulisan .....	3
<b>BAB II TINJAUAN UMUM LAPANGAN.....</b>	<b>5</b>
II.1.    Letak Geografis Lapangan.....	5
II.2.    Struktur Geologi.....	6
II.2.1.    Statigrafi.....	7
<b>BAB III DASAR TEORI MASALAH PEMBORAN DAN MINERALOGI</b>	<b>15</b>
III.I.    Masalah Dalam Pemboran .....	15
III.I.1.    Pipa Terjepit ( <i>Pipe Stuck</i> ) .....	15
III.I.2. <i>Shale Problem</i> .....	16
III.I.3.    Hilang Lumpur ( <i>Lost Circulation</i> ).....	25
III.II.    Mineralogi.....	29

III.II.1.	<i>Shale</i> .....	29
III.II.2.	Cation Exchange Capacity (CEC).....	34
III.II.3.	Hidrasi <i>Clay</i> .....	34
III.II.4.	<i>Problem Shale</i> .....	35
III.II.5.	Diagnosa <i>Problem Shale</i> .....	37
III.III.	Analisis <i>X-Ray Diffraction</i> (XRD).....	41
III.III.1.	Metode Analisis XRD.....	43
III.IV.	Methylene Blue Test (MBT).....	43
<b>BAB IV ANALISIS MINERALOGI UNTUK MENGIDENTIFIKASI SHALE PROBLEM PADA SETO SUMUR “MER-012” .....</b>		<b>48</b>
IV.I.	Data Sumur “MER-012” .....	48
IV.II.	Hasil Uji <i>Methylene Blue Test</i> (MBT).....	49
IV.III.	Hasil Uji XRD <i>Sample Cutting</i> .....	50
IV.IV.	Analisa Mineralogi dalam Mengidentifikasi Masalah <i>Shale Problem</i> Pada Setiap Trayek .....	54
<b>BAB V PEMBAHASAN .....</b>		<b>58</b>
V.I.	Identifikasi <i>Shale Problem</i> dengan Pendekatan Analisis Mineralogi Pada Sumur “MER-012”.....	58
V.II.	Pengaruh Kandungan Mineral dan Karakteristik Batuan Terhadap <i>Shale Problem</i> dan Permasalahan Pemboran Pada Sumur “MER-012” Pada Setiap Trayek .....	60
<b>BAB VI KESIMPULAN DAN REKOMENDASI .....</b>		<b>63</b>
VI.I.	KESIMPULAN.....	63
VI.II.	REKOMENDASI .....	63
<b>DAFTAR RUJUKAN. ....</b>		<b>65</b>
<b>LAMPIRAN.....</b>		<b>67</b>