

INTISARI

Sumur M-1 dan M-2 yang dijadikan obyek penelitian mempunyai zone produktif yaitu lapisan BRS 1,2,3 & 4. Lapisan ini terletak pada Struktur Paluhan Barat di Lapangan Pangkalan Susu, Sumatra Utara. Sumur sumur tersebut dipilih karena laju produksi minyaknya (Qo) mengalami penurunan (decline).

Penurunan produksi sumur-sumur tsb. dapat disebabkan beberapa hal diantaranya adanya hambatan berupa *skin* atau problem peralatan produksi. Untuk mengetahuinya dilakukan Pressure Build–Up (PBU) test. Dari analisa hasil PBU test tersebut didapatkan harga Skin Factor (S). Harga S yang berharga positip menandakan terjadi kerusakan formasi. Untuk sumur M-1 harga S : + 1,92 sedangkan sumur M-2 harga S: + 6,17 sehingga dapat disimpulkan bahwa sumur-sumur tersebut mengalami kerusakan formasi.

Untuk menghilangkan kerusakan formasi tersebut dilakukan Matrix Acidizing (pengasaman matriks) dengan menginjeksikan *mud acid* (HCl:HF) dengan konsentrasi 12:3 %.

Hasil evaluasi menunjukkan kenaikan produksi dimana hal ini membuktikan pelaksanaan Matrix Acidizing dapat menghilangkan kerusakan formasi tersebut.

Kenaikan total produksi minyak rata-rata sumur “M-1”: dari 13,21 bopd ke 21,61 bopd yaitu sebesar 8,39 bopd atau 64 %. Sedangkan sumur “M-2” mengalami kenaikan dari 10,54 bopd ke 14,47 bopd yaitu sebesar 3,39 bopd atau 37 %.

Dari perhitungan IPR dengan metoda Pudjo Sukarno didapatkan kenaikan rate produksi minyak untuk sumur “M-1” : sebesar 10,79 bopd atau 63 %. Sedangkan sumur “M-2” : sebesar 5 bopd atau 42 %.

Kata kunci : *penurunan produksi, Skin Factor (S), metode Pengasaman Matriks.*

ABSTRACT

Wells : “M-1” and “M-2” as the object of research has the productive zone BRS (Besitang River Sand) layers 1,2,3 & 4. This layer is on the Paluh Tabuhan Barat Structures in Field Pangkalan Susu, North Sumatra. These wells were chosen because its oil production rate (Qo) has been declined.

The production decline can be caused by several factors including *skin* or the production equipment problem. To find out the causes, Pressure Build-Up (PBU) test can be conducted which result in Skin Factor (S). Positive value of S indicating *formation damage*. Well M-1 result in S: + 1.92 and well M-2 result in S: + 6.17 . It can be can be concluded that the wells get *formation damage*.

To remove *formation damage*, Matrix Acidizing can be done. This method can injecting *mud acid* (HCl: HF) with a concentration of 12: 3%. The evaluation results showed an increase of production rate where this proves Matrix Acidizing implementation can eliminate *formation damage*.

Total increase (in average) oil production of well : “M-1” : from 13,21 bopd to 21,61 bopd is equal to 8,39 bopd or 64%. While Well “M-2” : production increase from 10.54 bopd to 14.47 bopd is equal to 3.39 bopd or 37 %.

IPR calculation by Pudjo Sukarno obtained increase oil production rate for well “M-1”: 10.79 bopd or 63%. While well “M-2” increase oil production as 5.0 bopd or 42%.

Keywords : ***production decrease, Skin Factor (S), Matrix Acidizing.***