

ABSTRACT

CV. Rejeki Wisnuadji, is a mining company stone located in Begelan, Purworejo. Mining activities include clearing of the land, stripping, exploitation, loading, and reclamation.

In carrying out the activities of mining, frequent accidents. The incidence of unsafe conditions were derived from state courts a dangerous and unsafe actions and ignore safety. Of unsafe conditions and unsafe actions that often result in work accident and eventually can cause the victim's death.

Potential accident occurred on the main road to the mine area. The road to the mine area is an area of work is most prone to among other things because of the condition of the roads is not solid, the bends are too sharp and the actions of the driver unsafe. While the work unsafe acts most often happens is a protective tool of self abandonment by workers. Mine accidents that occurred in the year 2019 there was 2 accident. The accident happened due to an unsafe actions which is caused by narrow road conditions, wavy road condition, the action is not safe, the driver is speeding up and lack of management oversight so that dump truck rolled over.

The completion of the work safety problem that occurs on a CV. Rejeki Wisnuadji is:

- 1. Do a repair on the unsafe conditions and unsafe actions in order that the safety risks can be minimized.*
- 2. Do the coaching plus skills or training to employees in accordance with the field work.*
- 3. Give socialization to the citizens about the mine so as not to enter the mining area.*